




H.C.B-B1091

SCANIA TRUCK FRONT WHEEL AXLES HUB EXTRACTOR



Caution: Before demolish the screws, you should loosen the wheel brakes first to keep it idle.

■ When SCANIA axle bearing is stuck due to it is over heat, use this kit with air wrench for labor savor and easier removal.